Field Remedy: 1620 Page 1 of 1

## Field Remedy: 1620

Subject: Z22SE Engine - Wrong oil level indication on oil dipstick

Models: Engines: Option:

Astra-G 2002...2004, Astra-G Coupe

2002...2004,Vectra-B 2001...2002,Vectra-C

2002...2004, Zafira 2001...2004

Z22SE,Z22SE,Z22SE,Z22SE

None

Complaint: After service oil change the oil level shown on the oil dipstick is approx. 4

mm above maximum mark.

Cause: Mentioned oil quantity (5 liters) in Service Literature is too high.

**Production:** not afftected

## Remedy:

Service oil quantity (incl. filter change) changed from 5 liter to 4,75 liter. Oil quantity between MIN and MAX on oil level dip-stick modified from 1 l to 0,75 l. Service literature and owners manual will be modified accordingly.

FunctionalGroup: J - Engine

**Complaint Group:** 23 - Wrong Indication

Trouble Code: None